










4x/6x




1x/2x



16x/24x




2x/4x
















$Z = 100 \text{ mm}$














$Z = 120 - 140 \text{ mm}$












10



11

